

EXAMPLES OF STRUCTURAL COLUMN DAMAGE

Botany NSW Australia

The following photos were taken at a major 3PL logistics centre in a Sydney suburb NSW.

- The columns that you see below are 15mm thick structural column approx 600mm x 300mm.
- The damage that you see was done by a forklift truck in separate incidents.
- These are just three of many damaged columns in that facility
- It is most likely that these columns will have to be replaced at a cost or approximately \$100,000 each.



Don't, take a risk. Order Protect-it MAXI structural column protectors now.

www.protect-it.com.au/maxi

Protect-it MAXI™ has international patents pending

All designs, trademarks and logos are copyright of their respective owners unless otherwise stated.

